

Wiper Blade Replacement to Reduce Ice Accumulation On Passenger-Side Wiper, Cascadia Vehicles

82-17

FLA COE
FLB COE
FLD Conventional
Business Class
FLC 112 Conventional

Century Class Conventional
Argosy COE
Cargo
Columbia

122SD and Coronado
Business Class M2
> Cascadia
108SD/114SD

**Freightliner
Service Bulletin**

General Information

In certain winter conditions, ice may build up on the outer tip of a standard 24-inch passenger-side wiper blade due to the curvature of the windshield on Cascadia vehicles. Replacing a 24-inch blade with a 22-inch unit (such as A22-68200-002) on the passenger side will increase the blade contact at the lower portion of the sweep, and minimize ice buildup while maintaining more than the 65% wiped area called for by the SAE Recommended Practice for vision zone coverage. This modification is voluntary.

Warranty

This is an informational bulletin only. Warranty does not apply.