

Subject

Camry U760 Transmission Oil Pan Leak

Market

USA

Service Category

Drivetrain

Section

Automatic Transmission/Transaxle

Applicability

2013-2015 MY Camry U760

APPLICABLE VEHICLES

2013-2015

Camry

CONDITION

Certain 2013-2015 Camry U760 vehicles may exhibit a transmission fluid leak from the transmission oil pan gasket.

RECOMMENDATIONS

- Please create a TAS case with transmission serial number and attach picture of condition with the following symptom coding;
 - Drivetrain → Automatic Transmission/Transaxle → Fluid → Leak
- Contact Technical Assistance (TAS) to submit details on any vehicle identified matching the condition described in this document prior to repair.
- If you are attempting to contact TAS on a weekend or TMS holiday, continue with diagnosis and submit the requested information on the next available work day. Retain all replaced parts and technician notes for possible review with TMS TAS Product Engineer.

Figure 1: Serial Number Location

TRANSMISSION MODEL	MODEL	MODEL YEAR	ENGINE	SERIAL NUMBER
U760E	Camry	2010 – 2014	2AR	Example: 13 A S 0001 P 13: Year of Manufacture A: Month of Manufacture (A - M, "I" not used) S: Transmission Model Code 0001: 4-Digit Serial Number P: Remanufactured Service Digit Location: On the Case Half Flange Above Differential, Slightly Rearward of Center (as shown)
	RAV4	2013 – 2014		
	Highlander	2009 – 2014	1AR	
	Venza			



LINK REFERENCES

This Tech Tip does not contain any link references

Subject

Camry U760 Transmission Oil Pan Leak

Market

USA

Applicability