



Service Bulletin

PRELIMINARY INFORMATION

Subject: Service Theft Deterrent Message In DIC Or DTC B2955 Stored

Models: 2015 Chevrolet Colorado
2015 GMC Canyon

This PI was superseded to update Warranty Information. Please discard PIT5382.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

The customer may state that the Service Theft System message displayed in the DIC. Further, the technician may find that DTC B2955 is stored in the BCM.

Recommendation/Instructions

Important: Do NOT replace any parts for this issue.

Advise to inspect the connections at the immobilizer and ensure there is enough slack in the harness with the column extended. Verify there are no proximity passes or fobs (except GM RKE transmitter) on the key ring. If present, they should be removed.

If no issue found and the code is history, engineering is investigating this concern and no further repair attempts or parts should be replaced at this time.

Warranty Information:

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7440790	Steering Column Lower Trim Cover Replacement	0.2 hours

Customer Information

If no issues are found and the code is history, please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern. Once a solution is available, this PI will be updated with additional details - allowing dealership personnel to contact the customer to schedule a service appointment and repair the vehicle.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION