

9003225

03/11/2015

MY2007 – 2015

JK

GPOP - Issue Review System

Part Number: 1XZ75FX9A\$, 1XZ76FX9A\$, 5SQ94SX9A\$, 5SQ95SX9A\$, 1JQ26SX9A\$, 1JQ27SX9A\$, 1JQ28SX9A\$, 1JQ29SX9A\$, 1PJ58SX9A\$, 1PJ59SX9A\$, 1QW84SX9A\$, 1QW85SX9A\$, 1QW65SX9A\$, 1QW87SX9A\$, 1XZ98FX9A\$, 1XZ99FX9A\$, 1YA00FX9A\$, 1YA01FX9A\$, 5SQ64SX9A\$, 5SQ65SX9A\$, 5SQ66SX9A\$, 5SQ67SX9A\$, 5SQ72SX9A\$, 5SQ73SX9A\$, 5SQ74SX9A\$, 5SQ75SX9A\$, 1XZ96FX9A\$, 1XZ97FX9A\$, 1HE00ZJ8A\$, 1HE01ZJ8A\$, 1JQ26ZJ8A\$, 1JQ27ZJ8A\$, 1JQ28ZJ8A\$, 1JQ29ZJ8A\$, 1QW84ZJ8A\$, 1QW85ZJ8A\$, 1QW86SX9A\$, 1QW86ZJ8A\$, 1QW87ZJ8A\$, 1YA02FX9A\$, 1YA03FX9A\$

Part Description: Soft Top Quarter Window or Rear Window

Issue Description: Please cycle the zipper 5-10 times when there is a single skipped zipper tooth.
~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.