

**SUBJECT****Valve Stem Replacement with Wheel Electronics****MODEL**

R55 (Clubman)

R56 (Cooper)

R57 (Convertible)

R58 (Coupe)

R59 (Roadster)

Produced from 09/09

R60 (Countryman)

R61 (Paceman)

Produced from 08/10

F55 (4-door Hardtop )

F56 (2-door Hardtop )


Produced from SOP

**SITUATION**

Tire pressure loss after replacement of the RDC/RDCi wheel electronics

**CAUSE**

Valve stems are not being replaced in conjunction of the RDC/RDCi wheel electronics replacement.

**INFORMATION**

**WARRANTY INFORMATION**

Not applicable.

[ Copyright ©2015 BMW of North America, Inc. ]