

**Measure no.**

US 59854260-04

**Subject**

Coolant tank/loss of coolant

**Status date (mm/dd/yy)**

9/3/15

**Status**

Accepted

**Organization**

US, MOT

**Date created (mm/dd/yy)**

9/3/15

**Created by**

Thomas Eichholz

**PQM Problem reference****Release date (mm/dd/yy)****Approved by****Dealer release**

Allow automatic release

**Vehicles affected****E series**

K47

**Engine**

4-ZYL

**Body****Production period (from/to)**

(mm/dd/yy)

/

**Comment on production period****Feedback (all cases relating to****measure up to) (mm/dd/yy)**

9/30/14

**Complaint**

Loss of coolant in the expansion tank. No visible traces on the vehicle.

**Cause**

Evaporation through the vent hole in the coolant expansion tank.

**Measure**

With verification of the complaint, replace the coolant expansion tank 17 128 545 627

along with the following part numbers:

17 13 8 562 618 Cap with support

61 66 7 067 184 Clip for hose

17 13 8 562 013 Vent hose

Defect code 17115248

Note: New parts are fitted as of production date 03/30/2015 VIN Z410049.

**Complaint****Fault location**

17/13 Expansion tank for

**Fault type**

Leak: Coolant

**Fault place**

coolant, motorcycle

---

**Cause**

#	Fault location	Fault type	Fault place
1	17/13 Expansion tank for coolant, motorcycle	Leak: Coolant	
Repair Task	Special Clearance	Area	
Replace	No	Powertrain	

---

**Fault code**

---

**Progman / DIS / ISTA / ISTAP**

System	State	Version
--------	-------	---------

---

