



Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

#### SUBJECT

**Delivery Stop: Check Air inlet grill in bumper, replace if necessary**

#### MODEL

F34 (3 Series Gran Turismo)

#### SITUATION

Under certain conditions, the additional radiator could not be cooled sufficiently. This could cause the engine to overheat. The engine power would be reduced and a Check Control Message would appear.

#### AFFECTED VEHICLES

This Delivery Stop involves F34 (3 Series Gran Turismo) produced from July 13, 2015 to July 18, 2015.

Vehicles which require this Delivery Stop to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

#### CORRECTION

Check the air inlet grills in the front bumper and replace if needed.

#### PROCEDURE

Inspect the vehicle for the properly mounted grille and replace as needed. See attached procedure.

**ONLY 7 Cars are involved for this inspection process.**

**Please do not order any parts until the inspection process is completed.**

#### PARTS INFORMATION

Part Number	Description	Quantity
51 11 8 057 199	Trim cover, grill, left	1
51 11 7 293 797	Partially open grid, left	1
51 11 7 293 792	Open grid, right	1

#### WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle/SAV Limited Warranty.

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

<b>Defect Code:</b>	<b>00 51 72 03 00</b>	
<b>Labor Operation:</b>	<b>Labor Allowance:</b>	<b>Description:</b>
00 63 727*	3 FRU	Check both air inlet grills
or		
00 63 728	3 FRU	Replace left or right grill (No M aerodynamic package)
or		
00 63 729	4 FRU	Replace both left and right grills (no M aerodynamic package)
or		
00 63 730	13 FRU	Replace left or right grill ( with M aerodynamic Package)
or		
00 63 731	14 FRU	Replace both left and right grills (with M aerodynamic package)

#### **ATTACHMENTS**

View PDF attachment [B512715 Attachment](#).

View PDF attachment [B512715 DS Legal](#).

[ Copyright ©2015 BMW of North America, Inc. ]