



SUBJECT

Speaker noise heard while traveling at highway speeds with the sunroof open

MODEL

F01 F02 (7 series)

F07 (5 series GT)

Vehicles produced up to February 28, 2010

SITUATION

While driving at higher road speeds with the sunroof open a distortion or pulsating noise can be heard from the central bass speaker(s).

CAUSE

Central bass speaker design

CORRECTION

If diagnostics find no other problem in vehicles where the symptoms can be reproduced, replace both central bass speakers (left and right side).

PROCEDURE

If you reproduce the speaker noise, run the test plan via symptom diagnosis. If no other problem is found then replace both central bass speakers (left and right side)

PARTS INFORMATION

Part Number	Description	Quantity
65 13 9 241 118 - Refer to ETK	Central Bass Speaker Left	1
65 13 9 241 117 - Refer to ETK	Central Bass Speaker Right	1

WARRANTY INFORMATION

Not Applicable

[Copyright ©2015 BMW of North America, Inc.]