



This Service Information bulletin supersedes SI B65 26 06 **dated October 2006**, and **replaces SI B65 23 05 dated November 2005**

NEW designates changes to this revision

SUBJECT

NEW The Disclaimer screen automatically disappears from the CID after 10 seconds

MODEL

NEW

E90 (3 Series Sedan)

E91 (3 Series Sports Wagon)

E92 (3 Series Coupe)

E93 (3 Series Convertible)

E60 (5 Series Sedan)

E61 (5 Sports Wagon)

E63 (6 Series Coupe)

E64 (6 Series Convertible)

With MASK, vehicles produced from March 2005 (Except E60 550i)

With MASK, E60 550i vehicles produced from September 2005

With SA609 CCC Navigation, vehicles produced from September 2006

NEW SITUATION

A change in the appearance of the CID (Central Information Display) when starting up, was made in production on the above mentioned vehicles. The change is as follows:

When turning on the ignition after the vehicle has been off for more than 5 minutes, a "Disclaimer" screen is displayed on the (CID), **and now disappears after approximately 10 seconds** without pressing the "ACCEPT" button.

Note: The "Disclaimer" screen can still be accepted manually as before by pressing the "ACCEPT" button.

NEW INFORMATION

An enhancement was made to the Car Communication Computer (CCC) and MASK (Multi Audio System Controller) in 2006 so the customer does not have to manually accept the “Disclaimer” screen each time.

Older vehicles prior to the production dates listed above that are programmed with ISTA/P 2.52 or higher will also get this enhancement.

NEW WARRANTY INFORMATION

Not applicable.

[Copyright ©2015 BMW of North America, Inc.]