

GPOP - Issue Review System

Part Number: 68005241A\$

Part Description: Fuel Control Actuator

Issue Description: If a vehicle arrives with an active MIL on for DTC P0088 - Fuel Rail Pressure Too High Bank 1, please do not replace any parts at this time. This DTC is currently being investigated to determine the root cause. Cummins Engineering would like to visit a dealership to acquire information from that vehicle. Please contact Christine Donegan at STAR at (866) 799-1692 ext 1257.~
If you do not receive an answer or call back within 15 minutes, proceed with normal diagnostics.~

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
