

## GPOP - Issue Review System

**Part Number:** 68127807A\$, 55111249A\$, 55111240A\$, 68260538A\$, 68260539A\$, 55111235A\$, 55111236A\$, 55111367A\$, 68111340A\$, 68111341A\$, 68111337A\$

**Part Description:** Distribution Housing, ATC HVAC controls, MTC HVAC controls

**Issue Description:** HVAC Unable to control temperature on one side only. Actuator fails to move through it's full range. DO NOT Replace the Distribution Housing or the HVAC control.  
Diagnose the Actuator for proper function. After performing the proper diagnostics, and Actuator is found to be defective, replace the actuator, then run a system calibration. Finally test for proper temperature control.~

~  
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.