

GPOP - Issue Review System

Part Number: 68232369A\$, 68214892A\$

Part Description: HVAC Blower and Wheel

Issue Description: HVAC blower motor is inoperative. Before replacing the blower motor please call one of these individuals:~

First call Brad Bartkowicz at cell (586) 808-4114~

If no answer, then call Vince Celli at cell (586) 630-8136~

If not response in 15 minutes, continue with repair.~

~_____~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
