

GPOP - Issue Review System

Part Number: 52121859A\$, 52122213A\$, 68005334A\$, 68071676A\$, 68210655A\$

Part Description: Exhaust system gaskets & clamps.

Issue Description: Anytime the turbocharger is removed/replaced, the turbocharger gasket, turbocharger outlet seal, and turbocharger band clamp must be replaced. In addition, if the front exhaust pipe is removed/replaced, always replace the turbocharger outlet seal and band clamp. The turbocharger gasket, turbocharger outlet seal, and turbocharger outlet band clamp will take a set when secured to the mating surface and is allowed to heat up and cool down. If the mating surfaces are separated, do not reuse these parts.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
