

GPOP - Issue Review System

Part Number: 68166807AB

Part Description: Brake booster

Issue Description: If brake booster loses assist and there is engine oil found in the booster, please replace brake booster, brake booster vacuum line 68082161AE, engine mounted vacuum pump PN 05047967AB, and master cylinder PN 68192615AA for ATX or PN 68192625AA for MTX. Please call Tim Parks at 248-245-9395 with the VIN, dealer code, and verify part numbers in order for parts to be Fastracked back to FCA for analysis. Thank you.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
