

GPOP - Issue Review System

Part Number: 68248448A\$, 05272781A\$, 05272782A\$, 68240967A\$, 68240965A\$, 68253167A\$,
05274579A\$, 68292954A\$, 05274578A\$

Part Description: Shock Absorber Assembly, Rear Suspension - Right Side.

Issue Description: Do not replace right rear shock assembly for noise. Please call Steve Lin office (248) 944-5959 or cell (909) 569-5117. If you do not receive a return call within 15 minutes, then proceed with the repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
