

11/14/15

MY15 JK

GPOP - Issue Review System

Part Number: 52060156A\$, 68003281A\$

Part Description: Wheel Speed Sensors

Issue Description: Before replacing the front wheel speed sensors, please call Gurdial Dhami at cell (226) 346-7919. If you do not receive a return call after 15 minutes, please proceed with repair.

~

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.