

11/18/15 MY15 DP, DS

GPOP - Issue Review System

Part Number: 68214859A\$, 68142577A\$, 68214856A\$, 68142576A\$, 68142575A\$

Part Description: Axle assembly

Issue Description: If replacing the rear axle assembly due to the R59 recall (DS axle Insufficient Axle Bearing Journal Hardness), please ensure that axle shafts are pitted and warrant axle assembly replacement per the recall service instructions. Mopar is committed to filling all orders within 48 hours. With a limited population of vehicles that will truly require an axle assembly a non-returnable policy is in place on this part and will be enacted to help protect inventory for vehicles that meet the inspection criteria within the R59 dealer repair procedure.

~

____~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
