

11/18/158 MY15 FF, KL, PF, RT, UF, WD, WK

GPOP - Issue Review System

Part Number: 68224166A\$, 68089094A\$, 68223053A\$, 68225055A\$, 68093422A\$, 68029719A\$, 05183147A\$

Part Description: HVAC Blower Assembly

Issue Blower Motor either making noise or is inoperative (even intermittently).

Description: Before replacing any of the part numbers listed above, please call any of the following people for each vehicle type. (If you don't get an answer within 15 minutes, then proceed with the repair.):~

WD/WK--68224166AB - Front Ken Deneau, cell (248) 765-0288~

68089094AA - Rear Pat Presti- cell (248) 379-0972~

KL/UF/PF- 68223053AB, 68225055AA Mark Ware, cell (248) 705-3469~

F500- 68093422AB, Matt Sasina, cell (248) 464-4982 or Bryan Bremer cell (248) 429-9014~

RT- 68029719AB - Front, Chad Holcomb at cell (734)-634-3679

05183147AA - Rear, Ken Deneau, cell (248) 765-0288~

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
