

12/9/15

MY13, 14 & 15 PF

MY14 KL & PF

GPOP - Issue Review System

Part Number: 06509898A\$

Part Description: Nut - Front Hub & Bearing

Issue Description: Whenever replacing the front Hub & Bearing Halfshaft Nut, make sure to torque to proper spec of 150 ft/lbs (200 Nm) and crimp according to procedure in TechConnect. (This torque is higher than other platforms). Failure to do so will result in eventual Hub & Bearing failure (noise).~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.