

12/16/15

MY14 KL

## **GPOP - Issue Review System**

**Part Number:** 1UT661X9A\$, 1UT701A9A\$, 1UT662X9A\$, 1UT701X9A\$

**Part Description:** ATX shifter assembly

**Issue Description:** Before this part is replaced for any issue please call John Grzecki on cell (248) 379-0969. If you do not receive a return call within 15 minutes, proceed with the repair.

Please be sure to accurately record any symptoms and DTCs identified with the scan tool and document them on the repair order.

~\_\_\_\_\_~

Contact Us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.