



CERTIFIED SERVICE CENTER



SOLUTIONS BUILT FOR YOU.

CPD-CS-NAP-F23 REV B 10/1/14

## Technical Service Bulletin

**Tech Service Bulletin #: 15-01**

**Date: 1/21/2015**

This bulletin is being sent to our customers who recently specified installation of the Bendix TABS6 roll stability system on their new Heil trailer(s). At the request of the supplier, this system includes a QRN valve (balancing valve) which may not be mounted per the recommendations of the supplier.

Heil Trailer requests that each trailer you possess listed on the original email, be inspected and Technical Service informed (800-400-6913 or [service@heiltrailer.com](mailto:service@heiltrailer.com)) as to the orientation of the part. If the valve is mounted incorrectly, Heil Trailer will send you a replacement valve and pay labor to have the valve replaced at a repair facility of your choice.

The QRN valve is located at the front of the running gear frame on the left hand/street side behind the bulk head fitting bracket (as shown in the picture on the second page of this bulletin). If the valve is mounted to where the exhaust port is pointed in any direction but downward, the valve is installed incorrectly and needs to be replaced.

Please inspect the valve and contact Heil Trailer Technical Service to proceed with either eliminating the trailer from the list or obtaining a plan for part replacement.

**Please contact Heil Trailer International, Co. Technical Services with any questions at 800-400-6913 or at [service@heiltrailer.com](mailto:service@heiltrailer.com)**




CERTIFIED SERVICE CENTER



SOLUTIONS BUILT FOR YOU.

CPD-CS-NAP-F23 REV B 10/1/14



Please contact Heil Trailer International, Co. Technical Services with any questions at 800-400-6913 or at [service@heiltrailer.com](mailto:service@heiltrailer.com)