



ROADSTER Fuel Vapor Canister Vent Hose Campaigns - Re-Notification (U.S. Models Only)_000109773_MES61Y015S02_en

[Printable Version](#)

Rate This Article



(Average Rating: No Rating)

Version 1

Language [English](#)

[Show Properties](#)

Article Detail

Dear Can-Am® Spyder® roadster Dealer,

In cooperation with NHTSA, BRP is re-notifying some customers that their vehicle may still be affected by:

[Safety Campaign Bulletin 2010-12:](#)

Fuel Vapor Canister Vent Hose Inspection/Replacement

Campaign: 2008-013, 2009-0009 and 2010-0017

What will BRP do?

BRP is sending Re-Notification Letters to the owners of a vehicle for which the above described campaigns are still pending.

What should you do?

Follow instructions in [Safety Bulletin 2010-12](#) that was originally sent to you in December 2012. These can also be found on BOSSWeb.

First Published By: Dany Davey on 02/27/2015

Last Modified By: Dany Davey on 02/27/2015