

# SERVICE BULLETIN

Classification: Reference: Date:

EL15-021 NTB15-068 August 7, 2015

# 2013-2015 SENTRA; RATTLE AND/OR BRAKE PEDAL VIBRATION INSIDE VEHICLE AT IDLE IN DRIVE

**APPLIED** 2013-2015 Sentra (B17)

**VEHICLES:** 

APPLIED VIN 2013-2014 Sentra (B17) All

**AND DATES:** 2015 Sentra (B17) Built before 3N1AB7AP(\*)FY 274591 / July 1, 2015

Built before 3N1AB7AP(\*)FL 668321 / July 1, 2015

#### IF YOU CONFIRM

• A rattle noise inside the vehicle coming from the engine compartment or instrument panel and/or a brake pedal vibration is present at idle in drive.

#### And

The engine room harness is in contact with the air filter assembly (Figure 1).




Figure 1


#### **ACTION**

Install a zip tie to secure the engine room harness to the driver's side frame rail.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

#### **INSPECTION OVERVIEW**

A rattle noise inside the vehicle coming from the engine compartment or instrument panel and/or a brake pedal vibration is present at idle in drive.



2/4 NTB15-068

#### **SERVICE PROCEDURE**

- 1. Remove the air cleaner assembly from the vehicle.
  - Refer to the Electronic Service Manual (ESM), section EM – Engine Mechanical for removal and reinstallation.



Figure 2

- 2. Loosely attach the zip tie to the engine room harness.
- 3. Snap the zip tie into the frame rail hole shown in Figure 3.




Figure 3

- 4. Tighten the zip tie around the engine room harness (Figure 4) and then remove (cut off) the excess zip tie.
- 5. Reassemble the vehicle in the reverse order.




Figure 4

3/4 NTB15-068

## **PARTS INFORMATION**

DESCRIPTION	PART#	QUANTITY
Zip Tie	24225-79960	1

## **CLAIMS INFORMATION**

Submit a Primary Operation (PO) type line claim using the following claims coding:

DESCRIPTION	OP CODE	SYM	DIA	FRT
Install Zip Tie	DX46AA	ZL	46	0.2

4/4 NTB15-068