

Classification:

Reference:

Date:

EL15-031

ITB15-030

October 28, 2015

2016 QX80; USB COVER NO LONGER FACTORY EQUIPPED

APPLIED VEHICLE: 2016 QX80 (Z62)

SERVICE INFORMATION

For Applied Vehicles, the USB cover (Figure 1) has been deleted (Figure 2).

The USB cover is no longer a standard component and should not be considered missing and should not be installed. Do not submit a warranty claim for installation of a missing USB cover.




Figure 1

Figure 2

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.