



Service Bulletin

E131

Section

Exhaust and Aftertreatment - 43

Description

DEF supply module for MX-13 EPA10 and EPA13 engines

Release Date

11/2/2015

Introduction

THIS BULLETIN IS INFORMATIONAL ONLY

High rate of Trouble Not Found (TNF) on the DEF Pump Modules (L074) on all vehicles built with an MX-13 EPA10 and EPA13 engine.

Resolution

INFORMATION ONLY

If the DEF Pump Module is found to be defective during diagnostics, use the procedures below to verify the fault before the DEF Pump Module is removed and replaced.

Procedure

Use the following procedures based on failure type:

- [Incorrect Installation](#)
 - [No-Prime Failure](#)
 - [Insufficient Dosing](#)
-

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed

through this system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2015 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).