



# Service Bulletin


## PRELIMINARY INFORMATION

**Subject:** Information on Installation of Stage One and Two Rear Wicker Bills on Spoiler

**Models:** 2015-2016 Chevrolet Corvette  
Equipped with RPO CFV or CFZ

**Attention:** This PI also applies to any of the above models that may be Europe, Japan and Middle East Export vehicles.

*This PI has been revised to add the 2016 Model Year. Please discard PI1478.*



During the installation of the rear wicker bills that are fastened on the rear spoiler, some technicians may revert to the use of power tools to tighten the fasteners.



The use of power tools should not be used due to the fact that this could lead to damage to the fasteners and/or the spoiler.

When installing the wicker bills onto the vehicle, it is recommended to hand start the fasteners before using the correct hand tools to torque the fasteners to the proper torque specifications.

Damage to the fasteners or the spoiler should not be submitted under warranty as the parts are dealer installed components during the pre-delivery process.

---

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION