



NUMBER: 05-011-15

GROUP: Brakes

DATE: October 03, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 05-002-14, DATED APRIL 16, 2014, WHICH SHOULD BE REMOVED FROM YOUR FILES. THIS IS A COMPLETE REVISION AND NO ASTERISKS HAVE BEEN USED TO HIGHLIGHT REVISIONS.

SUBJECT:

Front Brake Squeak/Squeal Noise

OVERVIEW:

This bulletin involves replacing the front brake rotors, front brake pads, and related hardware.

MODELS:

2013-2015 (PF) Dodge Dart

**NOTE: This bulletin applies to vehicles within the following markets/countries:
NAFTA, EMEA.**

NOTE: This bulletin applies to vehicles built on or before July 25, 2015 (MDH 0725XX).

SYMPTOM/CONDITION:

The customer may describe a front brake squeak/squeal high frequency noise in the 6-7 kHz range while stopping, noise may be intermittent (not every stop).

DIAGNOSIS:

If the customer describes the symptom, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68245323AB	PAD KIT, Front Disc Brake, Includes Hardware
2	68257206AA	ROTOR, Front
4	06510023AA	BOLT, Hex Flange Head, M14X1.50X30.00

REPAIR PROCEDURE:

NOTE: The brake caliper adapter bolts are one time use only, they must be discarded and replaced with NEW.

1. Replace the front brake Rotors with the NEW front brake rotors. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 05 - Brakes, Base> Hydraulic/Mechanical> Rotor, Brake> Removal/Installation> Front Brake Rotor.
2. Replace the front brake pads and hardware with the NEW front brake pad kit. Refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info> 05 - Brakes, Base> Hydraulic/Mechanical> Pads, Brake, Front> Removal/Installation.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
05-70-22-9N	Pads And Rotors, Disc Brake - Replace Front Set (2 - Skilled)	4 - Chassis Systems	0.8 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------