



RECREATIONAL VEHICLE SERVICE CAMPAIGN

May 1, 2015

SERVICE ADVISORY 15-229

«Dealer_Name»
 ATTN: Service Manager
 «Street»
 «City», «State» «Zip»
 «Country»

Dear «Dealer_Name»,

Reason for this campaign

It has been determined that on certain Fuzion FW product the attaching bracket for the ramp door patio steps have been incorrectly located. The location of the brackets only allow the step to be assembled and pinned to one bracket of the ramp door and patio railing.

The campaign population includes:

2015 Keystone Fuzion Chrome and 2015 Fuzion with Ramp Step Option in the Serial Number Range FF810473 – FF815634

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require inspection. **Important:** Please complete the service campaign on these units before retail delivery. Our records indicate the following unit serial number(s) are presently in your inventory or have been sold:

«VIN1»	«VIN2»	«VIN3»	«VIN4»	«VIN5»
«VIN6»	«VIN7»	«VIN8»	«VIN9»	«VIN10»
«VIN11»	«VIN12»	«VIN13»	«VIN14»	«VIN15»
«VIN16»	«VIN17»	«VIN18»	«VIN19»	«VIN20»
«VIN21»	«VIN22»	«VIN23»		

-- Serial numbers with '*' have been retail sold --

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the attached Service Advisory, please contact us at: **(866) 273-1452**

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
 Sales & Service Manager