

## *SB-10058062-1804*

**FORD:**  
2015 F-150

### **ISSUE**

Some 2015 F-150 vehicles equipped with an original Ford accessory tailgate liner may exhibit a warped tailgate liner.

### **ACTION**

Follow the Service Procedure steps to correct the condition.

### **SERVICE PROCEDURE**

1. Is the original Ford accessory tailgate liner warped?
  - a. No - this article does not apply.
  - b. Yes - proceed to step 2.
2. Inspect the tailgate liner outer edges. (Figure 1)




Figure 1 - Article 15-0076

3. Have the outer edges of the tailgate liner been modified?
  - a. No - proceed to Step 4.
  - b. Yes - this procedure does not apply.
4. Install a tailgate liner replacement kit. Refer to Section 3 - Warranty Coverages - Service Parts Warranty, of the Warranty and Policy Manual for ordering instructions.
  - a. Refer to the installation instruction sheet included in the kit.

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

OPERATION	DESCRIPTION	TIME
150076A	2015 F-150: Inspect And Replace The Tailgate Liner (Do Not Use With Any Other Labor Operations)	0.3 Hr.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
99000A38	34