



SB-10058079-2565

Service Information System

Technical Information Bulletin

Coolant Pipe Leaks Water on Certain CT660 On Highway Trucks{7000}

Media Number -TIBU8024-00

Publication Date -2015/03/05

Date Updated -2015/03/05

Caterpillar: Confidential Yellow

i06102556

Coolant Pipe Leaks Water on Certain CT660 On Highway Trucks{7000}

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TJD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEM1-UP; TEP1-UP; TGS1-UP; TJS1-UP; TGT1-UP; TSW1-UP; TEY1-UP; TSY1-UP; TEZ1-UP; TGZ1-UP)

Introduction

The problem listed below has an interim solution. Until a permanent solution is available, follow the instructions below.

Problem

The coolant pipe on the CT660 On Highway Trucks is failing due to holes in the welds or cracking at the welds.

Solution

Replace the failed coolant pipe with the current **398-5451** Kit-Heater when failure occurs.

[Copyright 1993 - 2015 Caterpillar Inc.](#)

[All Rights Reserved.](#)

[Private Network For SIS Licensees.](#)