

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR MARCH 2015**

44977 2014 Fusion, 2014-2015 MKZ Built On Or Before 1/17/2015 - Active Park Assist  
Finishes Too Early

Some 2014 Fusion and 2014-2015 MKZ equipped with Active Park Assist may exhibit a concern of the Active Park Assist system finishing or completing an active park assist event early without the vehicle becoming parallel with the curb. To correct the concern on Fusions, update the PSCM to the latest calibration using IDS version 94.03 or higher. For MKZ built on or before 1/17/2015, update the PSCM and the PAM to the latest calibration. If the MKZ is built on 12/2/2014 and through 1/17/2015, the latest PSCM software may already be installed, but the PAM should still be updated. Use causal part 3504 and applicable 12651D labor operations from section 10 of the SLTS manual.