

[Subscribe](#)[Share ▼](#)[Past Issues](#)[Translate](#)

Engineering/Operations Bulletin for Horton's Dealer Network.

[View this email in your browser](#)

Eng/Ops Bulletin

ECN 1415

March 9, 2015

Update

This ECN is for changing the booster pump installed inside the seat base to a new standard location under the truck.

The booster pump will be located under the body area of the seat base or heater location. The new location will prevent antifreeze from leaking inside the truck in the event of a pump seal failure. In addition, the new location will make it easier to access and service the pump.


There will be no change in the booster pump - the same product will be used. As always, make sure the pump is clamped and the lines are secure. Ensure the use of water proof connection on the electrical wiring.

Effective

March 16, 2015

Notes

N/A



Should you have any questions regarding the engineering update, you may address them to Eric Fisher at eric.fisher@hortonambulance.com.

Copyright © 2015 Horton Emergency Vehicles, All rights reserved.

[unsubscribe from this list](#) [update subscription preferences](#)

MailChimp