



TECHNICAL SERVICE BULLETIN

TSB#: 15-006

Job Code: 9803246

Flat Rate: 0.5

Date of Publication: August 2015

NOTE: This Technical Service Bulletin will be valid within (1) year from the original date of publication. REQUIRES PARTS TO BE ORDERED FROM Jayco for every unit.

SB-10058396-6017

ACTION REQUIRED: Install protective trim to large oval hole in the macerator hose storage box.

MODELS / UNITS:

2016 Precept Class A Motor Homes	31UL	G1UL	0051-0092,0094-0107,0114-0116,0118-0121,0123,0126,0128.0130,0133,0135, 0137-0138
	35UN	G1UN	0051-0069
	35UP	G1UP	0051-0063
	29UR	G1UR	0051-0070

KIT CONTENTS

Note: Kit can only be ordered using the order form included with this bulletin.

- 1 18" piece of TRIM,EDG .35X.55 BLK VNL/PLSTC

INSTRUCTIONS



Fig 1



Fig 2

- 1 Fig 1: Open the macerator hose storage compartment door.
- Fig 2: Pull the hose out of the compartment to access the large oval hole in the back of the box.



Fig 3




Fig 4

- 2 Fig 3: Place the 18 inch piece of trim lock around the hole and trim off excess.
- Fig 4: Shows the trim lock around the oval hole.
Trim should fit around the entire perimeter of the hole.
- 3 Coil the macerator hose back in the box and close the door.



903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-5861 • Fax (574) 825-7354

August 2015

Technical Service Bulletin Notification TSB #15-006

Name
Address
City State Zip
Country

Dear Valued Jayco RV Dealer:

Jayco has determined certain Model Year 2016 Precept Motor Homes require protective trim placed around the large oval hole in the macerator hose storage box to prevent damaged to the hose.

Our records indicate that the following Precepts are currently stock at your dealership and are included in this Bulletin:

Serial number

The coverage period for this Technical Service Bulletin is for one (1) year from the release of this notification. (August 2015- August 2016). If you have sold this affected vehicle, please contact the current owner regarding this Service Bulletin and process the Warranty Registration for this customer. All pertinent information regarding this Bulletin is on file under the Service and Parts Tab of Jayco Partners. If you have questions regarding this Service Bulletin, please contact Jayco Motorized Customer Service at 800-517-9137.

We apologize for any inconvenience this may cause. However, we are confident that this improvement will offer continued satisfaction with your customer's Jayco Precept.

Sincerely,

Jayco Motorized Group

Jayco Service / Parts
TSB Order Form
Fax (800) 825-8409



TSB # 15-006
2016 Precept Motor Homes
Macerator Box Trim

Dealer Name: _____ Date _____
Dealer Account Number: _____ Phone: _____ Fax: _____
Ship To: _____ P.O.# _____
Attn: _____ Ship Via: _____

Each unit serial number MUST be recorded when ordering.

Quantity Ordered	Serial Number of Unit (Last 8 Digits)	Part Number One Kit per Serial Number	U/M	Unit Price
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C
1		15-006JM KIT, MACERATOR BOX TRIM 9803246	EA	N/C

THESE PARTS CAN ONLY BE ORDERED USING THIS FORM.
You can not order using website.