

## **SB-10058436-6875**

### **ONLINE AUTOMOTIVE SERVICE INFORMATION FOR MAY 2015**

45126 2012-2013 F-150 4x4 - 3.5L - Transmission Fluid Leak - Built On 5/23/2012 And Through 6/3/2013

Some 2012-2013 F-150 4x4 with 3.5L built on 5/23/2012 and through 6/3/2013 may exhibit a transmission fluid leak from the bell housing. For visible leaks clean the location on the transmission and add Dye-Lite ATF/Power Steering Fluid Leak Detection Dye to the transmission fluid. Refer to the Workshop Manual (WSM), Section 307-01 Leakage Inspection. For vehicles built within the build dates mentioned please look closely to approximately the 4 o'clock to 6 o'clock area of the case ribs in the bell housing if the leak is coming out from this area replacement of the transmission case will be required refer to WSM 307-01 Transmission Disassembly. Use available service labor times. For vehicles that are not leaking in that specific case area please follow the appropriate WSM Procedure based location of the leak.