

Vehicle will not go over 5mph (8km/h) not related to countdown mode

Topic number	LI07.00-N-061850
Version	1
Design group	07.00 General
Date	07-30-2015
Validity	Sprinter 906
Reason for change	
Reason for block	

Complaint:

Vehicle will not go over 5mph (8km/h) not related to countdown mode

Cause:

During CDI Flashing the SCN coding of the "Maximum vehicle speed limit" setting has been reset to 8km/h

Attachments	
File	Description
Speedlimiter.JPG	Speed limiter setting

Remedy:

Re-SCN code the CDI control unit and change the Speedlimitter setting back to original setting

Symptoms
Power generation / Engine management / Engine performance / Goes into limp-home mode

Validity		
Vehicle	Engine	Transmission
Sprinter III	*	*

Attachments

Speedlimiter.JPG:

XENTRY

Note:

- The type-dependent and statutory maximum speed limit is specified via SCN coding based on the VeDoc
- The maximum speed limit can be reduced with this function at customer request
- The control unit uses the lower value in each case.

Overall procedure (overview):

- Manual entry Maximum vehicle speed limit
- Perform online SCN coding.

Name	Actual value
Maximum vehicle speed limit (SCN coding , VeDoc entry)	132km/h
Maximum vehicle speed limit (Customer-specific settings)	8km/h
Current maximum speed limit	8km/h

Question

Should the current speed limit be changed?