

SB-10058611-1612

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM FOR JULY 2015

45224 2015 F-150/Edge/MKX - 2.7L - built on or before 07/14/2015 - Diagnostic Trouble Code (DTC) P2282

Some 2015 F-150, Edge and MKX vehicles equipped with a 2.7L built on or before 07/14/2015 engine may exhibit DTC P2282 - air leak between the throttle body and intake valve. Before following normal diagnostics for this issue, check the brake vacuum booster line at the intake manifold for proper connection.