

**WIND OR WHISTLE NOISE FROM EXTERIOR MIRROR(S) AT HIGHWAY SPEED****TSB 15-0130****FORD:**

2013-2016 Escape

**ISSUE**


Some 2013-2016 Escape vehicles may exhibit a wind or whistle noise from the exterior mirror(s) at highway speed.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**


1. Remove the suspected mirror assembly. Refer to Workshop Manual (WSM), Section 501-09.
2. Remove the inner sail molded gasket/barrier. (Figure 1)



TB10746A

Figure 1 - Article 15-0130

3. Inspect the cavity below the electrical connector where the wiring feeds into the mirror head for the presence of a foam block to prevent air flow. Is the foam block present? (Figure 2)
  - a. Yes - proceed to Step 4.
  - b. No - proceed to Step 5.
4. Is the foam block positioned properly to seal off all 4 sides and corners of the cavity? (Figure 2)



TB10747A

Figure 2 - Article 15-0130

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

- a. Yes - this article does not apply. Refer to WSM, Section 5D1-00 for normal diagnosis.
  - b. No - properly position the foam block and proceed to Step 6. (Figure 2)
5. Install a foam block with locally available material and cut to the following dimensions 30 mm x 45 mm x 50 mm (1 3/16 X 1 25/32 X 1 31/32).
  6. Reinstall mirror.

Obtain Locally
Part Description
Foam Tape

OPERATION	DESCRIPTION	TIME
150130A	2013-2016 Escape: Install Foam Block Following The Service Procedure On One (1) Exterior Mirror. Includes Road Test. (Do Not Use With Any Other Labor Operations)	0.8 Hr.
150130B	2013-2016 Escape: Install Foam Block Following The Service Procedure On Both (2) Exterior Mirrors. Includes Road Test. (Do Not Use With Any Other Labor Operations)	1.1 Hrs.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage  
 Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
17682	07