



Service Bulletin

File in Section: -

Bulletin No.: PIP5288

Date: May, 2015

PRELIMINARY INFORMATION

Subject: Oil Leak From The Oil Filter


Models: 2015 Cadillac Escalade
2015 Chevrolet Silverado 1500 Suburban, Tahoe
2015 GMC Sierra 1500 Yukon Yukon XL
Built with RPO's 5.3L 6.2L L83 L86
With a engine build of K and between dates 15005 – 15117
St Catherine's engine plant= K
The numbers in the box are the date code

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

Customers may comment on an engine oil leak at the oil filter location of the oil pan.

With a engine build of K and between dates 15005 – 15117



4179080


St Catherine's engine plant= K

The numbers in the box are the date code

Recommendation/Instructions

If a loose oil filter adapter is found to be the cause of the engine oil leak,

Tighten oil filter adapter to 55 Nm or (40 lb ft)



4179079

Clean oil pan of any residual oil

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4065570	Oil Filter Adapter Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.