



# Service Bulletin

File in Section: -

Bulletin No.: P11508

Date: August, 2015

## PRELIMINARY INFORMATION

**Subject:** Windshield Wipers Intermittently Inoperative

**Models:** 2013 Cadillac ATS

**Attention:** This PI also applies to any of the above models that may be Export vehicles.  
**Condition/Concern**

Some customers may comment that the windshield wipers are intermittently inoperative in all modes. This may be caused by high resistance, or an open at ground G105 due to a faulty eyelet.

### Recommendation/Instructions

The crimp at the eyelet at ground G105 circuit 750 should be checked for high resistance or for being open intermittently by performing a wiggle test. A visual inspection of the eyelet and shrink wrap will not reveal an issue. If replacement is needed, select the straight 6 mm ring terminal (P/N 02984712) from tray 1 of the J-38125 Terminal Repair Kit.

Replace the eyelet following published repair procedures.

### Warranty Information

For vehicles repaired under warranty, use;

Labor Operation	Description	Labor Time
5430962	Ground Connection Repair	Use Published Labor Operation Time