

# TECHNICAL BULLETIN

## K243NAS1

### 26 MAR 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

### **SECTION: 412-01**

#### Service Action: Climate Control Center Vent Inoperative

### **AFFECTED VEHICLE RANGE:**

**F-TYPE (X152)**

**Model Year:** 2014

**VIN:** K00001-K07430

### **MARKETS:**

NAS

### **CONDITION SUMMARY:**

**Situation:** An issue has been identified on 2014 model year F-TYPE (X152) vehicles where the Climate Control System center vent does not go up and/or down or 'sticks' halfway and is unable to return to the closed position.

**Action:** Retailers are required to **HOLD** only affected vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

### **PARTS:**



**NOTE: \* when ordering parts, order only the expected percentage demand of parts identified**

DESCRIPTION	PART No. / SUNDRY CODE	QTY. / VALUE	EXPECTED % of VEHICLES REQUIRING PARTS*
Fascia vent (Black)	T2R11470PAJ	1	9
Fascia vent (Graphite Grey)	T2R11470LMF	1	11

### **SPECIAL TOOLS:**



**NOTE: this document is an 'Active Bulletin' that will display a functional programming shortcut if accessed within a diagnostic session using SDD.**

SDD with latest SDD-DVD and Calibration File

Jaguar Land Rover-approved Midtronics Battery Power Supply

Refer to Workshop Manual / Service Instruction for any required tools