

---

<b>Reference</b>	SSM72560
<b>Models</b>	XF / X250
<b>Title</b>	Check Engine Light illuminated with DTC P068A-00 stored in the PCM
<b>Category</b>	Engine
<b>Last modified</b>	17-Dec-2015 00:00:00
<b>Symptom</b>	499000 Basic Engine
<b>Content</b>	<p><b><u>Issue:</u></b> A Customer may express a concern that the Check Engine Light is illuminated with DTC P068A-00 is stored in the Power Train Control Module (PCM)</p> <p><b><u>Cause:</u></b> There is a CPU response time error during the vehicle shutdown procedure, this is a problem with the Power Train Control Module (PCM)</p> <p><b><u>Action:</u></b> A Technical Service Bulletin (TSB) will be published late in January 2016, potentially to coincide with DVD 144.04 for Jaguar model lines F-Type (X152), XF (250), XF (260), XJ (351) &amp; XE (760). The software fix for XF (250), has already been released, and is available on DVD 144.02</p>