

September 16, 2015

02376 Version 2

Safety Recall: Ignition Coils

Supersedes 15-060, dated September 3, 2015, to revise the information highlighted in **yellow**.

AFFECTED VEHICLES

| Year | Model | Trim | VIN Range |
|------|-------|------|---|
| 2015 | Fit | ALL | Check the iN VIN status for eligibility |

REVISION SUMMARY

Under REPAIR PROCEDURE, step 6 was added to complete the Vehicle Emission Recall - Proof of Correction certificate.

BACKGROUND

The noise suppression capacitors inside the ignition coils may degrade over time causing the check engine light to illuminate, the engine or fuel injection system to malfunction, or in severe cases cause the engine to stall.

CUSTOMER NOTIFICATION

Owners of affected vehicles will be sent a notification of this campaign.

Do an iN VIN status inquiry to make sure the vehicle is shown as eligible.

Some vehicles affected by this campaign may be in your new or used vehicle inventory. These vehicles must be repaired before they are sold.

Should a dealership sell an unrepaired vehicle that subsequently causes an injury or damage because of the recalled item, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify American Honda for any resulting claims. To see if a vehicle in inventory is affected by this campaign, do a VIN status inquiry before selling it.

CORRECTIVE ACTION

Replace the four ignition coils and, if necessary, clean the spark plug connection ends.

PARTS INFORMATION

| Part Name | Part Number | Quantity |
|---------------|---------------|----------|
| Ignition Coil | 30520-5R0-013 | 4 |

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

| Operation Number | Description | Flat Rate Time | Template ID | Failed Part Number |
|------------------|---|----------------|-------------|--------------------|
| 1175A2 | Replace the ignition coils and if necessary, clean the spark plug connection end. | 0.4 hr | 15-060A | 30520-5R0-003 |


Defect Code: 5YW00

Symptom Code: JT900


Skill Level: Repair Technician

REPAIR PROCEDURE


1. Disconnect the ignition coil connectors.



2. Remove the ignition coils.
3. Remove the spark plugs.



4. Inspect the connection end of the spark plugs.



- If the spark plug connection ends have corrosion on them, clean them with a commercially available cleaner, then reinstall the spark plugs and torque them to **22 N·m (16 lb-ft)**.
- If the spark plug connection ends does not have any corrosion on them, reinstall the spark plugs and torque them to **22 N·m (16 lb-ft)**.

5. Install the new ignition coils and torque them to **12 N·m (9 lb-ft)**.

6. **California residents only:** Fill out a Vehicle Emissions Recall – Proof of Correction certificate, and use JT9 as the recall number. Give the certificate to your customer, and advise him or her to keep it as proof that the recall was completed. Your customer will need to submit this certificate to the DMV only if the DMV requests it. If you need more certificates, use reorder number Y0657.

| Vehicle Emission Recall - Proof of Correction | | | | |
|--|-----------------------------------|------------------------------|--------------------------|-------------------------------|
| License Number | Make | Year/Model | Body Type | Vehicle Identification Number |
| | | | | |
| Manufacturer | | | Recall Number JT9 | |
| The above described vehicle has been repaired, modified and/or equipped with emission control devices to meet applicable California Emission Control Laws. | | | | |
| Dealer's Name | | Address, City, State and Zip | | |
| Date | Dealership's Authorized Signature | | | |
| | X | | | |
| Return this certificate to DMV only when required - otherwise retain for your records. | | | | |

Y0657 ACL 24832 (02/12)

END