

Reference	SSM72008
Models	LR4 / L319 Range Rover / L322 Range Rover Sport / L320
Title	V8 5.0L gasoline (AJ133) coolant pipe leak (LR018275)
Category	Engine
Last modified	05-Jan-2015 00:00:00
Symptom	Cooling System Concerns
Attachments	Pic.pdf

Content

Issue: Low coolant message displayed. A coolant leak is found from the seam on coolant pipe (LR018275). See the attached file for an example of the leak location.

Cause: A process issue at component supplier.

Action: Process improvements have been introduced to improve the seam welding. The end VINs for this issue are:
LR4 / Discovery 4 (L319) - LA695872
Range Rover (L322) - LM393638
Range Rover Sport (L320) - LS814557

The issue has been corrected for New Range Rover (L405) and New Range Rover Sport (L494).

