

Reference	SSM65557
Models	LR2 / L359 LR4 / L319 Range Rover Sport / L320
Title	Seat Switch,Recline Button Cap Replacement
Category	Body
Last modified	16-Mar-2015 00:00:00
Symptom	101000 Seating
Attachments	1Seat Switch.pdf

Content**Issue:**

Seat Switch Pack Recline Button cap is damaged or has broken / fallen off in service. (See fig.1)

Action:

Replace by pressing on new button cap Part No: LR045801 (See fig.2)



Fig 1



Fig 2