
| | |
|----------------------|--|
| Reference | SSM72008 |
| Models | LR4 / L319 Range Rover / L322 Range Rover Sport / L320 |
| Title | V8 5.0L gasoline (AJ133) coolant pipe leak (LR018275) |
| Category | Engine |
| Last modified | 05-Jan-2015 00:00:00 |
| Symptom | Cooling System Concerns |
| Attachments | Pic.pdf |

Content

Issue: Low coolant message displayed. A coolant leak is found from the seam on coolant pipe (LR018275). See the attached file for an example of the leak location.

Cause: A process issue at component supplier.

Action: Process improvements have been introduced to improve the seam welding. The end VINs for this issue are:
LR4 / Discovery 4 (L319) - LA695872
Range Rover (L322) - LM393638
Range Rover Sport (L320) - LS814557

The issue has been corrected for New Range Rover (L405) and New Range Rover Sport (L494).

