

# TECHNICAL BULLETIN

## LTB00833NAS1

### 17 SEP 2015



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

### **SECTION: 501-03**

## Tailgate Open Switch Replacement

### **AFFECTED VEHICLE RANGE:**

#### **LR2 (LF)**

**Model Year:** 2010-2015  
**VIN:** 148520-439912  
**Manufacturing Plant:** Halewood

#### **Range Rover Sport (LS)**

**Model Year:** 2012-2013  
**VIN:** 717166-814822  
**Manufacturing Plant:** Solihull

### **MARKETS:**

NAS

### **CONDITION SUMMARY:**

**Situation:** Where replacement of the tailgate open switch is required for any reason, only replace with the part listed in the Parts section below.

**Cause:** A new part and part number are available.

**Action:** Replace the tailgate open switch with the part number listed in the Parts section below.

### **PARTS:**

LR079909 Tailgate open switch Quantity: 1

### **TOOLS:**

Refer to Workshop Manual for any required special tools.  
 SECTION: 501-03

### **WARRANTY:**

**NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.**

**NOTE: DDW requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.**

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Tailgate open switch - Renew - LR2 (LF; L359)	<b>86.65.04</b>	0.4	28	LR042648
Tailgate open switch - Renew - Range Rover Sport (LS; L320)	<b>86.65.04</b>	0.2	28	LR042648

**NOTE: Normal Warranty procedures apply.**

**SERVICE INSTRUCTION:**

- 1 Replace the tailgate open switch (see TOPIx Workshop Manual, section 501-03: Power liftgate switch).