

Reference	SSM72405
Models	Range Rover Sport / L494
Title	Gear Lever Park Button Poor Finish
Category	Driveline
Last modified	03-Sep-2015 00:00:00
Symptom	504330 Automatic Shift Level/Linkage Concerns
Attachments	Gear Lever Park Button Finish.pdf (Gear Lever Park Button Finish.pdf)

Content **Issue:** A customer may report that the surface of the 'P' Button on the gear shift lever is wearing with loss of definition of the paint finish. Please view attachment that shows the condition.

Cause: Paint surface finish process

Action: If the concern has been reported by the customer, please replace the gear lever part number LR077066.

Note: A new paint refinish process has been introduced to prevent deterioration of the 'P' button on the gear shift lever from Vehicle Identification Number EA391028 onwards. Please only submit ePQR reports for this concern on vehicles post the above VIN.

