

<b>Reference</b>	SSM72445
<b>Models</b>	Range Rover / L405 Range Rover Sport / L494
<b>Title</b>	Continuous Squeal Noise from Rear High Performance Brakes L494 & L405
<b>Category</b>	Chassis
<b>Last modified</b>	30-Sep-2015 00:00:00
<b>Symptom</b>	301000 Service Brake System
<b>Attachments</b>	Pad Greasing - Squeal Fix.pdf (Pad Greasing - Squeal Fix.pdf)

**Content**

**Issue:**

A customer may report a continuous squeal noise from the rear high performance brakes.

**Cause:**

A lack of greasing during pad replacement OR brake usage characteristic.

**Action:**

Apply Molykote Cu-7439+ grease to the pad abutments as per the attached image.

**NOTE:** This is only applicable to the "J-Chamfer" pads as per the attached image.

