
Reference	SSM72547
Models	LR2 / L359 Range Rover Sport / L320
Title	L320 RR Sport & L359 FL2 - Tailgate Switch Malfunction
Category	Body
Last modified	07-Dec-2015 00:00:00
Symptom	112000 Latches/Locks & Security

Content Issue: Withdrawal of Technical Service Bulletin (LTB00833v2) relating to tailgate switch malfunction.

Cause: Part supply constraints.

Action: For any tailgate switch malfunction issues, please continue to replace with existing stock

- LR042648 (with reverse camera harness).
- LR020997 (without reverse camera harness).

The TSB relating to this issue has been withdrawn due to parts supply issues. JLR is working closely with suppliers to rectify this and will re-issue the bulletin as soon as parts become available to the markets.