

GPOP - Issue Review System

Part Number: 68210553A\$, 68210554A\$

Part Description: Panasonic 8.4" CTP Radio

Issue If a RE2 or RB5 radio-equipped vehicle is found to have both the radio not working &
Description: HVAC blower on high and will not turn off (may have DTC U0147). Please obtain a vehicle scan and report findings to Reggie Philip at cell (678) 330-0255 or Mike Boutorwick at cell (248) 736-7604 before attempting any repair. Engineering is currently root causing this issue and your assistance is greatly appreciated.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
